Electrabel









On-site specifications:

Les Awirs power station

LES AWIRS POWER STATION

Emergencies

Risk / Hazardous areas

Pipes

Work on gas installations



EVACUATION (ALARM)

In the event of evacuation:

Assembly area:

Mandatory badge swipe in the health unit courtyard











IN AN EMERGENCY:

Les Awirs, near SEVESO sites: (e.g. PRAYON, powder factory)

- □ If the SEVESO siren sounds = > containment
- Remain inside,
- Close doors and windows,
- Keep informed by radio,
- Do not use the telephone

SEVESO Alert: periodic onsite tests





IN AN EMERGENCY:

In the event of injury, for first aid:

- Health unit:
 - available onsite, at the plant entrance
 - key available at the CS and the guardhouse



Note: no medical staff on site.





IN AN EMERGENCY:

In the event of heart trouble:

Defibrillator:

- At the entry of the control station T5
- In the health unit











Natural gas

Risk: Asphyxia

Fire

Explosion

Prevention: Use personal protective

equipment (self-contained mask)







Heat

Burns

Steam

Burns

Hydrogen

Explosion





Explosive atmospheres (ATEX)

- Hazardous areas:
 - Natural gas: boiler, regulating station
 - Battery locations: H₂
 - Alternators: H₂
 - Pellet grinding





Gas substation hydrogen substation





Chemical products

Hydrochloric Acid (HCl) Caustic Soda (NaOH)









Basin Tank



Hazardous areas

Emergency stop cable = >



Conveyor belts



T4 Grinding mills

T4: Flying wood ash, powdery and caustic

= > risk of chemical burn



WORK ON GAS INSTALLATIONS

Conditions to be met:

- Authorisation required prior to work
- Circuits rendered inert and void of gas
- Very low voltage explosion-proof lighting
- Sufficient quantity of extinguishers on hand
- No smoking or producing fire
- Beware of inert gases (nitrogen, CO2), which are asphyxiants.





Vous avez l'énergie.

